


## Vis sans tête six pans creux bout plat - STHC

Hexagon socket set screw with flat point



Prix = le cent

| Ø | M 2 | M 2,5 | M 3 | M 4 | M 5 | M 6 | M 8 | M 10 | M 12 | M 16 |  |  |
|---|-----|-------|-----|-----|-----|-----|-----|------|------|------|--|--|
| s | 0,9 | 1,3   | 1,5 | 2   | 2,5 | 3   | 4   | 5    | 6    | 8    |  |  |
| t | 0,8 | 1,2   | 1,2 | 1,5 | 2   | 2   | 3   | 4    | 4,8  | 6,4  |  |  |
|   |     |       |     |     |     |     |     |      |      |      |  |  |
|   |     |       |     |     |     |     |     |      |      |      |  |  |
|   |     |       |     |     |     |     |     |      |      |      |  |  |

| Ø    | M 2 | M 2,5 | M 3 | M 4 | M 5 | M 6 | M 8 | M 10 | M 12 | M 16 |  |  |
|------|-----|-------|-----|-----|-----|-----|-----|------|------|------|--|--|
| L 2  | •   |       |     |     |     |     |     |      |      |      |  |  |
| L 3  | •   | •     | •   | •   |     |     |     |      |      |      |  |  |
| L 4  | •   | •     | •   | •   | •   |     |     |      |      |      |  |  |
| L 5  | •   | •     | •   | •   | •   | •   |     |      |      |      |  |  |
| L 6  | •   | •     | •   | •   | •   | •   | •   |      |      |      |  |  |
| L 8  | •   | •     | •   | •   | •   | •   | •   |      |      |      |  |  |
| L 10 | •   | •     | •   | •   | •   | •   | •   | •    | •    |      |  |  |
| L 12 | •   | •     | •   | •   | •   | •   | •   | •    | •    |      |  |  |
| L 16 |     | •     | •   | •   | •   | •   | •   | •    | •    |      |  |  |
| L 20 |     |       | •   | •   | •   | •   | •   | •    | •    | •    |  |  |
| L 25 |     |       | •   | •   | •   | •   | •   | •    | •    | •    |  |  |
| L 30 |     |       | •   | •   | •   | •   | •   | •    | •    | •    |  |  |
| L 35 |     |       |     |     | •   | •   | •   | •    | •    | •    |  |  |
| L 40 |     |       |     |     | •   | •   | •   | •    | •    | •    |  |  |
| L 45 |     |       |     |     |     | •   | •   | •    | •    | •    |  |  |
| L 50 |     |       |     |     | •   | •   | •   | •    | •    | •    |  |  |
| L 60 |     |       |     |     |     |     | •   | •    | •    | •    |  |  |
|      |     |       |     |     |     |     |     |      |      |      |  |  |
|      |     |       |     |     |     |     |     |      |      |      |  |  |
|      |     |       |     |     |     |     |     |      |      |      |  |  |

|                                                                                     |     |     |     |     |                 |                 |                 |     |    |    |  |  |
|-------------------------------------------------------------------------------------|-----|-----|-----|-----|-----------------|-----------------|-----------------|-----|----|----|--|--|
|  | 500 | 500 | 500 | 500 | 500<br>>L30=200 | 500<br>>L25=200 | 200<br>>L20=100 | 100 | 50 | 25 |  |  |
|-------------------------------------------------------------------------------------|-----|-----|-----|-----|-----------------|-----------------|-----------------|-----|----|----|--|--|